

CENTURY MINE STREAM MITIGATION PHOTOGRAPHS  
Piney Creek



Photograph: 60  
PCSR-15: Unsuccessful steep bank restoration



Photograph: 61  
PCSR-17: Unsuccessful steep slope restoration,  
log vane, and J-hook